

Changelog for TAHUNA capella (Beta release 19/12/2018)



Changelogs for this release, compared to previous Capella Live Release:

Fixed Bugs:

- Recalculated route not always logical when user left the track
- Unable to calculate route to the track
- Street not found when entering ZIP codes
- Map resource - No Bus Station POI
- Missing Thai letters
- Leaving and returning to a loop track
- TRANZX bike Motor power and current missing
- Routing sometimes not add turns for sharp left/right turns
- Wrong turn-by-turn instructions
- Wrong turn instructions on track navigation
- Birth date with year 1967 gets one day subtracted from the entry
- Speed computer does not show any digits after decimal point when using a speed sensor
- TO4 - Compass calibration not works
- Track navi - back to track - long red turn arrow is displayed (to the start of the track?)
- Zooming/panning is slower than on TO3X/Classic
- TO4 - compass is unusable
- "Distance to dest" can be wrong when leaving track
- EULA cannot be scrolled to the end of EULA
- Some points are discarded from the GPX file
- 4231 PRO SW - There's 2 Info buttons in Settings
- 4231 - Neverending ROM update for TO4
- Sometimes the Power off menu not open when pressing the HW button

New Features and Improvements:

- Multilanguage address search
- New maps (Panama, Costa Rica) need language localization
- New countries (Panama, Costa Rica) need country flag
- Support of new TO4 device
- Add flags for Central American Countries
- Add flags for African countries
- Set range for TO4 First batch production
- Change the company name in EULA and Copyright
- Device - NEW map poi category - tourism = attraction called type Landmarks
- Add new POI Category: Cycle Rental
- Defibrillator POI category
- Add flags for Asian countries
- Replace T icon with Turtle