



Changelog for TAHUNA capella (Beta release 14/03/2018)

New features/ changes:

- Improvements in the turn instructions display
- Show the name of the current location on the map can be enabled in the settings
- Train stations POI category
- Note „Please Wait“ when opening track

Solved issues:

- Error in map display - area problem
- Crash when delete the 3rd long track
- TEASI ONE³ eXtend: reconnection to both SAC and HR sensors after suspend has some issues
- TEASI ONE³X (Volt Edition for Fischer e-bikes): Crash on suspend/resume with old C17 display
- 12 hour format sunrise/sunset computer flipped at Taiwan
- Red circle appears on the direction arrow
- Device frozen opening several tracks
- No cadence information despite sensor being connected
- Device is blocked on "Loading Countries" (when an SD card is inserted at boot time with maps on it)
- Birth date before 1970 is not stored in profile
- Init sequence is not displayed removing the settings